

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:			
Company	Dennis Oakley Environmental Engineer		
OGM	Priscilla Burton Environmental Scientist III		
OGM	Pete Hess Environmental Scientist III		
OGM	Jim Smith Environmental Scientist III		

Inspection Report

Permit Number:	C0150017
Inspection Type:	COMPLETE
Inspection Date:	Thursday, January 05, 2006
Start Date/Time:	1/5/2006 8:45:00 AM
End Date/Time:	1/5/2006 11:50:00 AM
Last Inspection:	Wednesday, December 14, 2005

Inspector: Pete Hess, Environmental Scientist III

Weather: Sunny, clear; cold, 30's F. InspectionID Report Number: 833

1/13/2006

Accepted by: whedberg

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

153.90	Total Permitted
36.22	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership Types of Operations

✓ Federal	✓ Underground
State	☐ Surface
☐ County	Loadout
✓ Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is in the process of entering third quarter 2005 water monitoring data into the Division pipeline as of today's inspection. The Division notified the Permittee on December 23, 2005 that the EW Mines were still missing quite a bit of water monitoring information. Due to end of year vacations at most companies, no one was available to see that the required information had been submitted prior to 12/31. The Division feels that additional time is warranted such that this Permittee can meet this R645 requirement.

Ms. Priscilla Burton attended the inspection of the reclamation activities being conducted at the Des-Bee-Dove sediment pond.

Mr. Jim Smith was in attendance for the entire inspection, in order to pass necessary information to the new inspector.

The Des-Bee-Dove Mine was developed long before August 3, 1977; it is assumed that the sediment pond was constructed post-SMCRA to bring this site into compliance.

Inspector's Signature:		Date	Thursday, January 05, 2006

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150017 Inspection Type: COMPLETE

Inspection Date: Thursday, January 05, 2006

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	~		~	
2.	Signs and Markers	~			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation		~		
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	✓		✓	
14.	Subsidence Control		~		
15.	Cessation of Operations	✓			
16.8	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.k	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities		~		
18.	Support Facilities, Utility Installations		~		
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓			
22.	Other				

Permit Number: C0150017 Inspection Type: COMPLETE

Inspection Date: Thursday, January 05, 2006 Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

Vol. XVI of the MRP provides information on Phase III reclamation (sediment pond). Map 700-1 illustrates the proposed reclamation topography for the pond area.

3. Topsoil

No further material will be removed from the subsoil stockpile. The existing soil will be graded to resemble the surroundings, and then covered with the substitute topsoil that is stockpiled immediately adjacent.

The Permittee indicated that the knob adjacent to the dam embankment will be used in its entirety (approximately 1,300 cu yds) rather than removing only 600 cu yds for substitute topsoil purposes. Movement of this additional fill will be used to blend the western slope into the disturbed area, while maintaining separate drainage ways between the main channel and the highway diversion.

4.a Hydrologic Balance: Diversions

The diversion ditch between the sediment pond access road and the subsoil pile was clear and capable of functioning as designed. Snow remains where direct sunlight does not intercept the east side of the ditch. Mr. Oakley pointed out the sediment demarcation line in the mine site main channel. The site has not seen a major event since the site reclamation was completed in June of 2003. Hence, minor events are flushing small amounts of sediment down the main channel, which helps lock the riprapped channel bottom in place.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The reclamation of the Des-Bee-Dove mine site sediment pond was initiated on November 28, 2005. Two large dozers from Nielson Construction were working the pond bottom this day pushing material up the NE slopes to achieve 2H:1V slopes having a 1.3 static safety factor. Due to the close proximity of one of the undisturbed drainages which will be routed through this reclaimed area, it may not be possible to achieve a 2H:1V slope at one of the cut banks which were created to build this pond. Hence, some Mancos shale may have to remain exposed, such that a stable fill is created. The undisturbed areas of the basin in which the pond exists are surrounded by vast areas of exposed Mancos shale. Hence, the remaining exposed cut bank should help the reclamation of this disturbed area blend with the undisturbed.

4.d Hydrologic Balance: Water Monitoring

The only water monitoring site for the Des-Bee-Dove Mine is the UPDES outfall from the sediment pond, which is, as noted elsewhere, undergoing reclamation. There was no discharge from the pond in October. There was no water in the pond during today's inspection. There was no flow coming into the reclaimed channel at the mine site this day.

Permit Number: C0150017 Inspection Type: COMPLETE

Inspection Date: Thursday, January 05, 2006 Page 4 of 4

8. Noncoal Waste

A six-inch aluminum pipeline was exposed by the reclamation activities at the sediment pond. Mr. Oakley indicated that the line will be removed from the site for disposal.

10. Slides and Other Damage

The reclaimed area within the mine site disturbed area perimeter did not show any signs of fill area failure. No unstable conditions were noted.

12. Backfilling And Grading

The two dozers operating within the sediment pond began recovery of material from the pond embankment during today's inspection. Although a lot of material still remains to be moved, the Permittee anticipates that this reclamation work will be completed by January 31, 2006. The east slope has been backfilled to its final grade. Topsoil will be replaced and then a small amount of material from above the cut will be brought down to blend with the fill. Small channels in the fill will be armored to protect the soils from flows that will gravitate toward them. The smaller channels will be protected where necessary. The main channel is established on bedrock in the middle of the pond. There are three areas shown on Map 700-1 that will be riprapped as per the typical design found in Figure 7-3. Bedding will be employed where the undisturbed main drainage channel meets the reclaimed area. Design for the bedding is provided on page 7-15 of the hydrology section of MRP Vol. XVI.

13. Revegetation

Table 3-1 of MRP Vol. XVI contains the approved reclamation seed mix for the sediment pond area. Mr. Oakley developed this mix through consultation with Dr. Patrick Collins, of Mt. Nebo Scientific, and Ms. Jerriann Ernstsen of DOGM / SLO. Two species in the mix were noted growing vigorously on the disturbed slope above the pond: mat saltbush and shadscale.

Over the past couple of weeks, wet pond soils were mixed with the subsoil and pushed up against the slope over the past weeks. As a result, good compaction has been achieved.compacted. The compacted soils will be covered with at least 6 - 8 inches of substitute topsoil and gouged. The Permittee is aware of the negative effect of compaction on vegetation establishment.

16.a Roads: Construction, Maintenance, Surfacing

The access road to the sediment pond will be reclaimed during the retreat process from the pond area.